

Photo guide for Copperplus application



The picture on the left shows old antifouling that needs to be stripped off before Copperplus can be applied.

This can be stripped easily with our Antifouling remover - Strippit

The picture on the right shows how effective Strippit antifouling remover is at removing old antifouling without damaging the gel coat.



Photo guide for Copperplus application



The picture on the left shows the hull fully stripped of its old antifouling

Once the hull is stripped to this standard it is then time to apply the Safeguard PS - Primer for Copperplus.

The picture on the right shows the hull with its first coat of Copperplus applied.

The first coat of Copperplus plus has been applied on top of Safeguard PS - Primer for Copperplus.



Photo guide for Copperplus application



The hull has now had 2 coats of Copperplus and is finished and ready for use.

As you can see Copperplus gives a nice finish while incorporating long lasting antifouling effects thus reducing the amount of time lifting and cleaning which entails to a huge saving in time and expenditure.

You can find all the information regarding Copperplus at :

www.reactiveresins.com Phone : 01208 26499